

March 29, 2007

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. 0072, ROTOR

HEAD HUB PLATES

This letter transmits the cancellation of Service Directive Bulletin No. 0072. Since the initial release of this Service Directive Bulletin (SDB) in 1986, there have been no additional reports of cracked hub plates as described in the original SDB. All of the periodic inspection checklists in the applicable maintenance manuals for the F-28/280 Series aircraft models require inspecting the main rotor hub for cracks.

TECHNICAL PUBLICATIONS
ENSTROM HELICOPTER CORPORATION