

February 3, 2005

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. 0013,

INSPECTION OF IDLER TENSION STRAPS, P/N 28-13236.

This letter transmits the cancellation of Service Directive Bulletin (SDB) No. 0013. This SDB has been superseded by SDB 0095.

TECHNICAL PUBLICATIONS ENSTROM HELICOPTER CORPORATION