

February 3, 2005

TO: Recipients of Enstrom Helicopter Service Directive Bulletins.

SUBJECT: CANCELLATION OF SERVICE DIRECTIVE BULLETIN NO. 0038,

INSPECTION OF STABILIZER ATTACH TUBE.

This letter transmits the cancellation of Service Directive Bulletin (SDB) No. 0038. This SDB has been superseded by SDB 0076.

TECHNICAL PUBLICATIONS ENSTROM HELICOPTER CORPORATION